

Спецификация на ОА сгг сферично съединение

15.01.2008

Spare- (E) and Wear part (V) list

1

Sales Doc.1207911		Ite 000010 Code		ALSTOM Power Systems GmbH	
Material 117766					
Plnt 1000 Usage 3 Alt.		Document			
Reqd qty 1 ST		Base qty 1, ST			
Level	Spare Assem	Quant Un	Material Description Industry Std Desc. Basic material	SortStrng	
..2	V X	1,000 ST	112260 Driving unit horizontal		
..2	V X	1,000 ST	112261 Driving unit vertical		
....4	E X	1,000 ST	52965 Cage with cover, compl	4.1	
....4	V X	1,000 ST	101756 Guide tube	4.3	
.....5	V	1,000 ST	100412 Slide layer		
....4	V	4,000 ST	6430 Washer	4.6	
....4	V	2,000 ST	104873 Bolt 12 H11x 30 Form B DIN 1444 ST	4.9	
....4	E	2,000 ST	856 Split pin 3,2x20 DIN 94 STGALZN	4.10	
....4	V	8,000 ST	6427 Washer Ms 24x 13x 0,5	4.11	
....4	E X	1,000 ST	58648 Blowing tube guide for WLB CB100	4.20	
..2	E X	1,000 ST	54496 Frame cpl. for WLB CB100	3	
...3	V X	1,000 ST	67661 <i>сфера</i> Hollow ball positive pressure	2.1.4	
..2	E	1,000 ST	110519 Fan ELMO 2BH 1500-7AH06-Z 0,75 KW 3,8 / 2,2 A		
..2	V	1,000 ST	44362 Hose pipe DN32 T1 1450 1 1/4"		